

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SR02794CH

This certificate issued to Donaldson Company, Inc.
17891 Chesterfield Airport Road
Chesterfield, Missouri 63005

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 29 of the Federal Aviation Regulations. See Type Certificate Data Sheet H9SW for complete certification basis.

Original Product-Type Certificate Number: H9SW
Make: Bell
Model: 230, 430

Description of Type Design Change:

Installation of an Inlet Barrier Filter (IBF) System in accordance with Donaldson Company, Inc. Installation-IBF System Drawing No. 118000-010, Revision C, dated August 27, 2009, or later FAA Approved revision.

Limitations and Conditions:

1. The installer must determine whether this design change is compatible with previously approved modifications.
 2. FAA Approved Rotorcraft Flight Manual Supplement, AFS-BH430-IBF-FMS, Revision IR, approved on December 22, 2009, or later FAA Approved revision, is required.
 3. Instructions for Continued Airworthiness, AFS-BH430-IBF-ICA, Revision A, dated August 24, 2009 or later FAA Approved revision is required.
 4. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.
- ...End...

This certificate and the supporting data, which is the basis for approval, shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 2, 2008

Date reissued: February 21, 2017, November 15, 2017

Date amended: September 23, 2011

Date of issuance: December 22, 2009

By direction of the Administrator



for 
(Signature)

Roy E. Boffo III
Manager, Propulsion & Program Management Section
Branch Chicago Aircraft

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.