


REV.	DESCRIPTION	DATE	BY
06	Removed text from I 2/5 barcode text box, ECO 2003A1394	8/26/03	PS
7.	Added base label P475857, ECO 04A1014	3/22/04	CW
8.	Removed code 39 b/c ECO 2006A0169	9/19/05	gk
9.	Update base label per ECO 2006A0935	3/31/06	TJM
10.	Added trilingual languages for Qty and Country of Origin ECO 2007A0717	2/26/07	GK




Quantity

I 2/5 bar code.

- First three digits will always be 1 07 unless otherwise indicated.
- Last digit is a check digit and is figured out by the computer.


-Barcode must be 1" in height

Placement of bar code label on carton in which length panel is longer than width panel



Label is placed in the bottom right hand corner on the length panel of carton

Placement of bar code label when length and width panels are of equal size.



Label is placed in the bottom right hand corner on panel of carton.

Country of Origin in three languages:
 Reference EN0504011 for country of origin spellings.

NOTES:
 1) Quiet zones must be .25" or greater on each side of bar codes

Item	Description
	P476828 Label Format
1	P475857 Base Label
2	P471967 Base Label (alt)
3	P469137 Base Label (alt)
4	P475858 Base Label (alt)
5	P474638 Base Label (alt)

Dimensions:	Cross Web	Repeat
Inches:	4	2.5
Millimeters:	101.6	63.5
	Max O.D.	8.0"
	Name:	CJW
	Release Date:	5/21/01

Title: Label Format - Dana
 (barcode for six digit part #'s)

Part Number:	Rev.
P476828	10
SHEET	1 OF 1